13 FEB 1946

OPERATIONS RECORD BOOK

R.A.A.F. Form A.50

of (Unit of Rammation) No: 354 (Transport) Squadron

No. of Sheet 86

Placo Summary of Events References to The first of the tenth of the mental for - - Tittaleza (41617...) Jan. 46. Appendices Flt. Owens 0.0. Signals section, on return from Schedule run to Morotal and return, Townsville. submitted report on laxness of ground signals en route.

A/F/Lt. A.W. Bonham. (1488) arrived on posting from 6 AD. as Squadron Engineering Officer.

F/o F.S. Hardy(1402) Nav B arrived on posting from 2PD. for flying duties.

F/o J.E. Fountair(32156) Engineering Officer posted to 2 PD. for termination of appointment: W. Yo K.F. Wardle(427109) W. OA.G. posted to 5 PD. for discharge. The following were appointed for Squadron Duties; Messing Officer F/o. J.H. Roberts. (34766:)
Welfare Officer F/L. W.D. Hart. (42241) Ass. Welfarë Officer.P/o. M.J. Martin.(444B97!)
Operations Officer. F/L. J.N. Stacy.(417244.)
Canteen Officer. F/o. M.F. Burcher.(424146.) W/o. Lewis N.A. (Pilot) posted from 3PD. for flying duties. F/d. Collopy returned from Melbourne with two engines for Maintenance Section. F/o. J.H. Crawford Nav. B. (427443) posted from 2RPP. for flying duties. F/Lt. Eddy and F/Lt. W. Davidson appointed members of a Court Martial held at RAAF Station Garbutt. F/Lt. McCollough and S/o. Moran of RAAF Station Garbutt Accounting Section inspected Squadron Orderly Room, Accounting and Messing Sections. G/Capt. Henry (DRM) W/Cmdr. Richmond (Forward Echelon) S/Ldr. Barrat (D. Eqpt) S/Ldr. Avery (DRM) & F/Sgt Clarke (DRM) visited Squadron for purpose of inspecting maintenace Section.

F/o. G.E. Dunoan (410656) W.O. A.G. posted to 1PD. for termination of appointment. F/o. S. W. Simmonds (419484) Nav. B. attached to 50. T. U. to undergo Transport Loran Course. W/o. Brooks (415301) W. O. A.G. posted to 5PD. for discharge. (429631) W/o McLeod E.M. and (13036) F/Sgt Grieve D. (W.O. A.G's) posted to 1PD. for discharge. \$427102) W/o. Morris G. A. WOAG posted to 5 PD. for discharge. (449225) F/sgt. Hamilton R. A. Nav. B. arrived on posting from 200 Flight for flying F/Lt. S.R. McKinnon (405232) Nav. B. arrived on posting from 3 PD. for flying duties. 162083 Opl. A. H. MoD. (Cypher Assistant) presented with Good Service Card at Commanding Officers Parade in recognition of services rendered during Cherical arfare Research at the Inter-Services Australian Field Experimental Station, Proserpine. F/Lt.K.R.Ponlson (426758) Nav.B. arrived on posting from 6Squadron for flying duties. S/Ldr.Tarleton, Area Inspector of Accounts inspected Squadron. F/Lt.M.B. Jones D.F.C. (406597) Nav.B. attached to 5 O.T.U. to undergo Transport Lorand Course. F/o.G.R.Dumont (12011) Nav.B. arrived on posting from 2 PD. for flying duties. S/Ldr. MoCarthy, Directorate of Telecommunications RAAFHQ visited Squadron for purpose of giving information of Signal proceedure. The first effect of the recent heavy rains has been felt with both roads (running from the Camp area to the strip and from the camp area to town) being partly submerged. The only means of getting through is by Motor 23. F/Lt. L.R. Smith (427565) Pilot. and P/O W. A. Jennings (415992) Pilot. posted to 33 Sqdn. F/Lt. R.G. Oracknell (421173) Nav. B. attached to 5 O.T.U. to undergo Transport Loran 24. Letter of thanks received by C.O. from G/Capt. Henry (DRM) for co-operation and assistance during recent visit to Squadron on investigation into Maintenace position. F/Lt. Muir assumes Command of Squadron Detackment at Morotai in place of F/Lt. EcRobbie who has returned to the Squadron. 43x

References to Appendices

Sqdn. Ldr. Commanding No. 35(Transport) Squadron.

Serviceability. Dakota aircraft 69.5% Tiger Woth Nil. Aircraft Strength Dakota 13.

Ambulance 1. Tanker Refuel (2A) 2(A) Trucks Heavy Gen, Serv. 1. Gen. Serv. 2. W/T (G2) Tractors Grawler 2.30HP 1. 4 Wheeler Serv. 1. 4 Wheeler Towing 1. M/Cycle & S/Car. 1. Strength. Ambulance 1. 5 tn. Chev Truck 2. 4 tn. Chev Truck 1. 30wt ditto 2. 3ton Ford

Stakeside 1. Jeep 1. 15 owt Fargo Utilhty.1. 15 owt Ford Ut. 1. W/T tender.1.

Motor Transport. Establishment.

Motor Cycle and Side Car. 1.

COMMANDING OFFICER'S REPORT

JANUARY - 1946 5 MAR 1948

1. OPERATIONAL.

The total hours of 1086 for the month is considered low, but there has been a rise of 3% in serviceability above the last months

This drop in hours has been due to a deliberate curtailment of some schedules which was found necessary owing to the extra time taken to complete inspections brought about by the shortage of starr, and delay in obtaining spare parts.

Following the Signals Report submitted last month S/Idr. McCARTY from R. A.A.F. H.Q. is carrying out an investigation into the signals position on this Squadron's Routes and it is hoped that some improvement will be effected as a result.

There has been one engine failure during the month, the aircraft being landed safely at DARWIN. North Western Area are carrying out the engine change which resulted and negotiations are now being made for North Western Area to submit a defect report.

2. SERVICEABILITY.

The percentage of 69. % is considered satisfactory and has been explained fully in the Engineering Officer's Report.

3. EQUIPMENT.

Although some improvement has been shown, inabilities still exist in some important items.

There seems to be some relief showing at Air Depots in respect to ancilliarary equipment for 1830 90 C Engines as this Squadron has acquired 2 engines recently with all necessary equipment for a quick change.

4. HOTOR TRANSPORT.

All vehicles performed satisfactorily throughout the month, maintenance is dealt with by one Hitter D.M.T. assisted by Fitters lik from the hangar.

This misemployment again slows aircraft serviceability up, and it would be appreciated if one more Fitter D.M.T. could be posted to the Squadron.

5. HYGIENE.

This is becoming increasingly difficult with the wet season at hand.

large numbers of personnel are again being misemployed in spraying swamps etc.

There appears to be a plague of flies at present and they are particularly bad around the camp and kitchen areas. All precaution are being taken but with the open nature of the buildings, ordinary spray is not considered adequate and application is being made for D.D.T. to treat the kitchen areas.

6. MESSING.

Some difficulty is being experienced in obtaining sufficient quantities of fresh vegetables and fruit, and it is hoped that the position will be relieved during February.

This has been explained fully in the Messing Officer's Report

(K.S. BROW)

Contanding No. 35 (Transport) Squadron.



OPERATIONS RECORD BOOK

R.A.A.F. Form A.50 (Feb., '99)

of (Unit of Formation) No. 35. (Transport) Squadron

Place TOWNSVILLE	Date Fbb 46	Summary of Events	References to Appendices
***************************************	1.	\$/LDR A.W. Page (292610) and F/Lt J.P. Graney (407944) attached C.F.S. POINT COOK with effect from 4th February to undergo No. 4 Instrument Course C.F.S. POINT COOK	·
e Discontinue de la companya del companya del companya de la compa		with effect from 4th February to undergo No. 4 Instrument Course.	:
	-	415054 W/O Barrow W C. Anckor w/o wo Tanbuldment Jourse.	• •
se benevi de la cama d	!	granted commission with rank of P/O on probation. WH-CIV flows by F/O B Clarks (ADTAIN)	,
	}	VH-CIY flows by F/O P Clarks (ATTACT)	
The state of the s		approximately helf way between Ambon and Darwin when excessive vibration commenced in the starboard engine necessitating it to be throttled back	,
Marine and the second of the s		In the starhoard engine recession in the stark of the violation commenced	
		the nort engine almost completely and the various of various and back. A few minutes later	
<u>G</u>		again to maintain height 177 amaintain and the opened un	
		succeeded in reaching Darwin. The port engine with a broken grank shaft was changed	•
		and the starboard with a created with a created with a broken crank shaft was changed	
1	4.	F/O G.J. Mitchell (410686) after 3 years as Adjutant of Squadron was posted for discharge. Duties as Adjutant taken over by F/L A L. Bischarge posted for	
The Control of the Co		discharge Duties as Addutant to years as Adjutant of Squadron was posted for	
and the second s	5.	discharge. Duties as Adjutant taken over by F/L A.L. Ripper (406189).	
		VH-RFH a No. 38 Squadron direct landed at Garbutt U/S and was repaired by this Unit.	
in the second	6.	Successful guest night held at Officers: Mess.	
en e		The Directorate of Flying Safety visited Garbutt and a conference was held with	
Commence of the commence of th		them by the Commanding Officer, S/Ldr K.S. Brown (A.F.C.) (260680).	
en de la companya de	1 1	Information received of intended increase of Morotai Detachment for the purpose of conveying No 81 Wing to Japan.	
•	8.	conveying No 81 Wing to Japan.	
general and a second	"	VH-RFA, VH-RGC departed with 4 crews, ground personnel and Equipment for Morotai to	
		take part in move of Occupation Forces to Japan.	
High record of the control of the co		VH-RFF, flown by F/O S. J. C. Reading (415444) and F/L. D.P. Sheriden (415689), returned	
en monte en la maria en la participación de la companya del companya de la companya de la companya del companya de la companya	9.	Continues because Australia:	
	16.	Continuous heavy rains.	
e germenter er e	11.	Weather conditions prevent aircraft taking off. Area S.O. Works inspected camp site.	•
ericania de la compansión de la compansión La compansión de la compa	12.	Continued heavy rains prevented operations. Two more pirerest allerest taking off. Area S.O. Works inspected camp site.	
eri erika da	1 1 - 1	TWO MOTE SIMMORE STANDARD OF W.	•
	16.	Mackay. arburretor faults. RFQ forced landed at Rockhampton - No damage.	
	1 70.	I/ULL HOODER (ADAPER) in the pure	
	1.78	Melbourne with A/Com. Bladen and other Officers.	
	20.	F/O McKeown of No. 5 Com. Unit reported on attachment for Adjutent Duties.	
	20.	F/Lt. Vaughan from Directorate of Eng. & Main. visited Unit.	
Yes Commission when some and the second second Second second	1 E-L - 11	3 4 74 AZZAMA TAMA - 1 4 4 4 1 10 10 10 10 10 10 10 10 10 10 10 10 1	
Mary Transfer of the second and the second	52.	WH-RFM Of the first of the firs	
ا المناموراً الشام المناسلة الم	27.	Arrangements made to supply six sircraft to accide from special Japanese detachment.	
	20 1	Arrangements made to supply six aircraft to assist in evacuating R. A. A. F., personnel insl number of applicants for Tax	•
enterior estados de estados de estados en la composição de la composição de la composição de la composição de La composição de la compo	eo	inal number of applicants for Interim Air Force to	•
]3	rom Madang. inal number of applicants for Interim Air Force to date, Aircrew 25. Ground Staff 30. STABLISHMENT AND STRENGTH as at 28th February.	
		STABLISHMENT AND STRENGTH as at 28th February. ESTABLISHMENT Officers 47 STRENGTH Officers 76 O.R.'s 252 AINTENANCE During the month 1 major inspection 10.05 hours.	
And the second s			
		OF LOUISINGTH Officers 76	
	1	AINTENANCE During the month 1 maior 1 0. R. 's 255	
	O	O.R.'s 252 STRENGTH Officers 76 O.R.'s 252 O.R.'s 255 ut. Also 3 engine changes. ERVICEABILITY DAKOTA 686	.,
The second secon	- <u>s</u>	ERVICEABILITY DAKOTA 689 TICED NOMING CONTINUE C	
atti dilimenta manda a anti da a a a a a a a a a a a a a a a a a a		IRCRAFT STRENGTH DAKOTA'S 17	
	P	OSTINGS. During the month CO Table MOTH. 1.	
The state of the s	D	spots for discharge The Tennel were posted to their respection	in the to constitution
	30	AINTENANCE During the month 1 major inspection, 10 minor inspections were carried ut. Also 3 engine changes. ERVICEABILITY DAKOTA 68% TIGER MOTH 67% IRCRAFT STRENGTH DAKOTA'S 13. TIGER MOTH. 1. OSTINGS. During the month 90 personnel were posted to their respective Personnel of Other Ranks. The number was comprised of 33 Officers 18 N.C.O.'s and	ودولا الشيار المستعلمية أبأ دارج عامات
	The first and characters of the	The state of the s	
新疆的 基础是一个是一个一个一个			مورات در المهاول احتيالها علائم والأوراد و المعادل. الدروان
- September 2 1 (44) · Calendary (34) · Span (34) · Span (44)	وَّ مِنْ الْحَدِّ مِنْ فَكِيْلَ سِيْرُولِ وَاللَّهِ عَالِي		

Place Date		Summary of Events	References to	
t the enterior of the territory that is a consequence of the consequen		the second the second s	Appendices	
And the same of th		MOTOR TRANSPORT.	and the second s	
Manager & Section of Section 22 (2)	ļ	ESTABLISHEND.		
Control of the Contro		Ambulance 1. Swington		
Have been the second of the se		Tunker definelize (20) Chanden a room of		
		Gon Convice 1. 3 Th Chev Planck 2	TANT TO	
		Gen Service 2. H/Cycle & S/Car 1. 4 In Chev Truck 1. 15 Cut Ford 1/T (G2)	Util. 1.	
opp for the second seco) /= \n=/	٠	
Services and the service of the serv		5 In Rord S/Side 1. H/Cycle 6. 3/0	Jar 1.	
Company of the Compan				
details Teat	•			
de partie				
			•	
Andrew Commencer		y .	• • • • •	
142 (17 TS)				
	. [
The same former former to grow the same of			**	
			• • •	
	•			
	.			
symmetric services and the services				
Tribusti de la comercia		A COLA I		

(R. YOURS)

T/Commanding,
No. 55 (Transport) Squadron. Flight Lieutepant,

APPENDIX "A"

COMMANDING OFFICER'S REPORT

FEBRUARY - 1946.

L. OPERATIONAL

The comparatively low total of 986 hours flying for the month is attributable principally to Maintenance as explained, in the Engineer Officer's report attached.

During the first week of the month six aircraft were despetched on Detached service at Morotai and have since been employed in moving Occupational Forces to apan.

A partial engine failure occurred in aircraft VH_RFQ en route from Mackay to Archerfield. A successful landing was accomplished at Rockhampton and the defective engine was subsequently replaced.

2. SERVICEABILITY & WAINTENANCE

Serviceability for the month was 68% as compared with 69.5% for the preceding month and is considered satisfactory.

The detachment of six aircraft at Morotal complete with full maintenance crews to participate in the movement of Occupation Forces to span has entailed curtailment of work on Major Overhauls. This has resulted in five aircraft now being due for 350 hourly inspections. As explained in the Engineer Officer's report further restriction to Maintenance has been caused by the necessity to misemploy 30 airmen in Barracks and Messing duties.

3. EQUIPMENT

Inabilities of demands placed for some important items of equipment have occurred but as stated in the Equipment Officer's report, this position should improve during the current month through overseas requisitioning.

4. MOTOR TRANSPORT

Servicing of Motor Transport has been aggrevated by the movement of personnel under Demobilisation and it has been necessary to misemploy two fitters lie to assist with the maintenance.

5. HYGIENE

In order to maintain a satisfactory state of Hygiene, it has been necessary to misemploy a number of Maintenance personnel for Barracks duties which in turn hampers aircraft servicing.

During the month a small quantity of D.D.T. was procured and has been used to spray the Kitchens and Messes.


6. MESSING.

Monthly Messing report for FEBRUARY is attached hereto.

...Flight Lieut

T/COMMANDING,

No. 35 (Transport) Squadron



OPERATIONS RECORD BOOK.

SAPR 1948

SAPR 1948

HE CHOUSE TERS

R.A.A.F. Form A.50 (Feb., '33).

of (Unit or Formation) No. 35 (Transport) Squadic HEADQUARTE

No. of Sheet 87

Nacc.	Date.	Summary of Events.	References to Appendices.
And the second second	MARCH,	1946.	
TOWNSVILLE.	1	Commanding Officer, S/Idr. K.S. BROWN (260680) A.F.C. proceeded to MELBOURNE on special	randon de la company de Mandaga de la company de la compan
		duty. Flight Lieutenant R. YATES (406606) appointed to temporary command.	
designation mater to see the east	3	Heavy raine. Campai to flooded.	
	1 4	Flight Lieutenent R. W. DRAKE-BROCKMAN, Aircraft VH-RFP, recco. of flooded area between	
mandam pagency of a management of the control of th		BOVEN and HOME HILL.	The state of the s
		Flight Lieut chan+ R.W. DRAKE-BROCKMAN (427616) Aircraft VH-RFP dropped supplies to	a comment of the comment of the comment of
		stranded rail motor mear CAPE CLEAVETAND.	
marged http://march.com/states/articles		Received instructions to move to compatte recently vacated by No. 1 R.P.P.	Committee of the Commit
	[6	Flight Lieutenant M.M. TAYLOR (406583) Aircraft VH-RFP, reccc. of INGHAM and HOME HILL	
And the particular destruction of the contract		Area's with official press photographers. Supply drop penicillin at both places.	The second secon
t and the second se		S/Ldr. K.S. BROWN (260680) A.F.C. returned from duty in MELBOURNE.	
	11	Tiger Noth Al7-628, 37238, Warrant Officer BENNIS F.V. Pilot made emergency landing	
A compression of the contract	·	AYR with supply penicillin.	
	l 갶	Received notification of proposed dirbandment of Unit wer 30th March, 1946.	
common common company when distinguishing acting against the company of the compa	15	Commenced move to new campaite.	
e. Philosophy in the Philosophy and Albanda appropriate and the state of the state		Flight Lieutenant S.G. TOWNSEND (413452) D.F.C. in Aircraft VH-RFB, supply drop vital	
	76	rations COEN.	
Market of the party of the control of the second of the se	16	Instructions to disband unit wef. 31st March, 1946.	
	18	Flying Officer T.S. JUDD (6647) completed dual instructions and sent solo.	
	19 22	Completed move to new campaite.	
The same transfer the company of the constraint of the same transfer of	- 66	Aircraft VH-RFN, Flying Officer S.J.C. READING (415444) Pilot departed for GUILDFORD on detachment.	•
	23		
	26	Successful mess function - Opening Officers Mess new camp. Squadron Leader K.S. BROWN (260680) A.F.C. attended Unit Commander's farewell to	
		A. O. C. Departed 0900 home.	
	27	Squadron Leader A.W. PAGE (292610) returned from successful completion No. 4 Instrument	
the same and the s		Plying Course.	
	31	VH-RFF, Flight Lieutenant S.G. TOWNSEND (413452) D.F.C. (Pilot) departed BRISBANE on	
and the state of t		last scheduled flight.	•
Approximately and the second s		-Flight Lieutenant J.P. GRANEY (407944) returned from successful completion Instrument	
	<u> </u>	Flying Course.	
and the second section of the second section is the second section of the section of t		TOTAL FIXING HOURS FOR MONTH: DAKOTA 569.45: TIGER-MOTH 11 hours.	*** ***
		ESTABLISHMENT AND STRENGTH as at 31st March, 1946.	
		ESTABLISHMENT. Officers 33 STRENGTH. Officers 61	• ••
and the second s	=	0.R. 202	
7	1	MAINTENANCE. During the month 2 major inspections and 7 minor inspections were carried	•
and the same of th		out, also I double engine change.	
		SERVICEABILITY. Dakota 636. Tigor Noth 70%.	
		AIRCRAFT STRENGTH. Dakota's 13. Tiger Moth. 1.	
		-POSTINGS. During the month-72-personnel were posted to their respective Personnel	
•		Depots for discharge. The number was comprised of 10 Officers. 15 N.C.O's and 47	
		Other Ranks.	n i game i se gri se di mid i gris da i di di distribi na di
			*** ***** **** *** *** *** *** *** ***
		A .	
		Transfer for the first has been suppressed as the suppressed of th	
e e o	1 1	••••••••••••••••••••••••••••••••••••••	
A STATE OF THE PARTY OF THE PAR			ran a con estado de la compansión de la co
	_		

Place.	Date.	Summary of Events.	References to Appendices.
Made de la companya d			
O		MOTOR TRANSPORT.	
nika malagangan yang anda membana kanpanan seriasi sengan sebagai sebagai sebagai sebagai sebagai sebagai seba Sebagai			A second
nama and an angles and the same and the sam		CHIPTIANT	e Printern van 1960 van de 196
nga atau samananan menenganan saman a mungan peneranan saman saman saman saman saman saman saman saman saman s Saman saman sa		ESTABLISHURFT.	The second of th
ka fili Maria da	Ambula	rice l <u>Tractors</u> . Ambulance . 1 Jeep Refuel 2a : Crawler 2.30HP 1 3 tn. Chev. Truck 2 15 Cwt. Far	л . 1
The second secon	- Truoke	Reavy u Theoler Serv. 1 4 tn. Chev. Truck 1 15 Cwt. For	d-Util-l
S. (1) 1 Hadrida (1994) 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 19 Hadrida (1994) 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 1994 1	Gen. S	ervice 1 4 Wheeler Towing 1 . 3 Cwt. Chev. Truck 2. W/T. Tender ervice 2 L/Cycle & S/Car. 1 3 Tn Ford S/Side 1 L/Cycle & S	/car 1
	W/T. (G2) <u>1</u>	*****
A VAN HAND IN DESCRIPTION OF THE PROPERTY OF THE PARTY OF THE PROPERTY OF THE PARTY			The state of the s
			A STATE OF THE STA
	1		•••
a de la composição de l		and the second	The second second second second second second
ing digital series and the series of the ser			Met record on the terms of a second of a contract of a
erigi erika da karantaria d Mangana da karantaria da k			Service of the service of the serv
i garagan da sangan da sangan Sangan da sangan da s		and the contract of the contra	The state of the
	The spring commensus	Squadron Leader,	
		(K.S. BROWN) Commanding, No. 35 (Transport) Squadron.	
		No. 35 (Transport) Squadron.	membersyan y de son en other en best proper yaap de teen een persone de sander de sander
	<u> </u>		
		ad talenda talenda a de la calenda de la ca	The survey
The control of the co		<u>and and a standard to the literal and the factor of the factor of the standard of the standar</u>	
		terres de la finación de la companya de la company Constituto de la companya de la comp	7 Tel
		to encomparative and the second of the secon	
	1 2 cm (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	erakan keranggan dan perkanggan dan beranggan dan keranggan dan beranggan dan beranggan dan beranggan dan bera Beranggan keranggan dan beranggan dan beranggan dan beranggan dan beranggan dan beranggan beranggan dan berang	A Train of the standard of the second
SAN CARREN		and sample to the control of the con	
CHECKER CONTRACTOR	1477年19日本 1987年19日本	n met Menden et en	त्रात्त्र के त्रात्त्र क्षेत्र स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स्ट्रिस स्टब्स
MILADERA DE CARA DE CA	1972 (C.)		

CONTROL OF LOST 8 BESON

MARCH . 1946

The serviceability and general maintenance of all aircraft is considered satisfactory giving consideration to the rate of postings for discharge and the inexperience of personnel.

All Squadron schedules have now ceased and disbandment has commenced. However there are still three aircraft away on detachment. One aircraft is operating with 81 Wing, escorting Mustangs to Japan. It is not known when this will return as it is understool that it is now at BOFU waiting for Mustangs to become serviceable.

It is anticipated that this will not jeopardise disbandment to any great extent.

The MOROTAL Detachment is being closed as soon as possible. This should be completed during the next two weeks.

Some unserviceability has caused delay there, together with the aircraft being delayed at BOFU.

EQUIPMENT.

This appears satisfactory. Issues and demands have been curtailed due to the disbandment of the Squadron. Allottments are expected for all aircraft during the coming month.

MESSING.

The standard of rationing has been satisfactory with the inclusion of supplementation. Added to that, conditions at the new camp are much better which lends to the improvement of the preparation of meals.

(K.S. BROWN)

Connending,

No. 35 (Transport) Squadron.